

Secure the UVHT on the PCI slot



Adjust the fan postion



Plug the connector to the power supply unit